












ASSEMBLY INSTRUCTION

FRDT1 - SINGLE DRESSING TABLE


HARDWARE LIST

<b>1</b> 	<b>2</b> 	<b>3</b> 	<b>4</b> 	<b>5</b> 	<b>6</b> 	<b>7</b> 
Bolt $\Phi 8 \times 80 = 4$ pcs	$\Phi 8 = 4$ pcs	$\Phi 9 \times \Phi 10 = 4$ pcs	M8 = 4 pcs	$\Phi 10 = 8$ pcs	1 pc	M4 $\times$ 45 = 4 pcs


PART LIST

 FRDT1	<b>A</b>  LEFT FRAME 1 PC	<b>B</b>  BAR SUPPORTS = 2 PCS	<b>C</b>  TOP & RIGHT FRAME = 1 PC
--	--	--	---


Step 1



Step 2



Step 3



Step 4

