









# ASSEMBLY INSTRUCTION

PVH35 - 5'0" LOW FOOT END SLATTED BED


## HARDWARE LIST

NO	HARDWARE NAME	IMAGE	QTY (PCS)
1	NUTS M8*13		8 PCS
2	HALF MOON WASHER M8		8 PCS
3	RING WASHER M8		8 PCS
4	SPANNER 13		1 PC
5	ALLEN KEY M4		1 PC
6	METAL THREAD M8*80		8 PCS
7	BOLT M6*50		2 PCS
8	WOODEN DOWEL		4 PCS
9	SCREW 4*30		26 PCS




## PART LIST


**A** HEADBOARD = 1 PC




**B** FOOTBOARD = 1 PC




**C** SIDE RAILS = 2 PCS




**D** SLATS = 13 PCS




**E** CENTRE SUPPORT RAIL = 1 PC




**F** CENTRE LEGS = 2 PCS



## STEP 1




## STEP 2




# ASSEMBLY INSTRUCTION

PVH35 - 5'0" LOW FOOT END SLATTED BED


## STEP 3



## STEP 4



## STEP 5



## STEP 6

